100K Linear Potentiometer
(271-0092/0211/1714/1715/1716) **Schematic Drawing** **Faxback Doc. # 18001**

THIRD ANGLE PROJECTION



NOTE

TERMINAL MATERIAL- IRON



This potentiometer has three leads; however, it does not have a grounding tap. To connect the potentiometer, use two leads for the connections, connecting to the center lead and either the left or right lead, depending on whether the user wants it to increase resistance by turning clockwise or counter-clockwise.